LOCKHEED AIRCRAFT CORPORAT	ION	ENGINEERING STUDY  CHANGE PROPOSAL  X				
DATE 1-16-62	AFFECTS:	WSPO	<b>x</b>	PROJECT X	]	
NAME OF MAJOR COMPONENT AIRPLANE	PART OR LOWEST SUBA	SSEMBLY	PART N	O. & MODEL C	OR TYPE	
TITLE OF PROPOSAL : AUTOPILO	T HEADING SYNCHRONI	ZER ADDITIO	ON .	, i s		
NATURE OF PROPOSAL:						
SEE PAGE	: 2				Y =	
		,		•		
t .						
	•			χ.	n na	
			•		**********	
REASON FOR PROPOSAL:						
	•					
礁				• •	·	
ESTIMATED COST AND TIME						
ES ADDITIONAL FUNDING REQU	IRED:					
ESTIMATED COST FOR KITS	OR PARTS: SEE PA	GE 2				
(CD)	IRED: NONE (	SP-1923)			ما المساحة والمساود ومودوران	
CP ADDITIONAL FUNDING REQU						
ADDITIONAL FUNDING REQUIREMS AFFECTED BY PROPOSAL:						
ADDITIONAL FUNDING REQUIREMS AFFECTED BY PROPOSAL :  SAFETY MISSION PERFORM OPERA ANCE PROCE	DURE   CHANGE   WEIGHT &	SUPPORT	NANCE L	VICE FLIGHT	MAINTE- NANCE MANUAL	
ITEMS AFFECTED BY PROPOSAL :	DURE CHANGE WEIGHT & BALANCE	SUPPORT			MAINTE- MANCE MANUAL	
ADDITIONAL FUNDING REQUIRED SAFETY MISSION PERFORM OPERA PROCE	DURE CHANGE WEIGHT & BALANCE	SUPPORT PR	NANCE L	IFE MANUAL	MANUAL	
ADDITIONAL FUNDING REQUIRED BY PROPOSAL :  SAFETY MISSION PERFORM OPERA PROCE TIVENESS X X X	PLISH CHANGE IN FIELD	SUPPORT PR	NANCE COCEDURE COCEDU	IFE MANUAL	MANCE MANUAL	

SP-E-1A

() ()

3. Jan 62 PAGE 1 OF 2

## NATURE OF PROPOSAL

- 1. The autopilot control gyro amplifier (WSPO/P/N 114705-02R345 and Project P/N 114705-02R338) will be modified by replacing the existing 976 directional gyro with a heading synchronizer. These units will be modified at LEAR and re-identified. A minimum amount of aircraft wiring will be required at the autopilot terminals in the nose area.
- 2. On four aircraft only (Serials 56-6701/368, 56-6721/388, 56-6722/389, and 56-6954/394) a stepdown transformer must be added to accomodate this autopilot modification in order to retain the additional heading reference capabilities of these four aircraft.
- 3. Prepare and issue a Service Bulletin and fabricate the necessary Kits. It will be necessary for a sufficient number of spares to be returned for modification in order to establish a turnaround schedule for Kit shipment.

## REASON FOR PROPOSAL

į,

( )

To improve the autopilot's capability to fly corridor missions. After the synchronizer is installed, the autopilot will be improved as follows:

- a. Allow immediate use of autopilot (re-engagement) after use of compass fast slave. The two and one half minute time delay will be eliminated.
- b. Maintenance malfunctions will be reduced due to elimination of extra autopilot directional gyro.

## ESTIMATED COST FOR KITS OR PARTS

SIĄI	
	*To be initiated by and accomplished per Depot Rework Order Requests Contract SP-1923, "REPAIR OF CUSTOMER PARTS - COMMON"
STAT	There are approximately 100 ca. amplifiers in the total assets, therefore a budgetary estimate of will apply to this job. Expenditures will extend into FY 1963.
* *	